


FIG. B

PILASTER ASSEMBLY



* .60 FOUNDATION-GRADE TREATED WOOD